

**Work Order ID 73449**

Thursday, September 01, 2011 7:31:06 AM



Page 1

Item ID: D3465-1

Accept



Setup

Start



Revision ID:

Item Name: Washer

Stop



Start Date: 8/31/2011 Start Qty: 20.00



Cust Item ID:

Required Date: 9/16/2011 Req'd Qty: 20.00



Customer:

Reference:

Approvals: Process Plan:

CL

Date: 11/09/01

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3465	Rev B

100



Hardinge CNC LATHE SMALL

Hardinge

Hardinge CNC Lathe Small

Memo

0.00

ark 11/09/01 / 20 ✓  
 11/09/01 ✓ 20 ✓

QC2- Inspect parts off machine FAI/FAIB

0.00

110



Memo

ark 11/09/01 / 20 ✓  
 11/09/01 ✓ 20 ✓

QC

Quality Control

120



QC8- Inspect parts - second check

0.00

QC

Quality Control

Memo

0.00

ark 11/09/01 / 20 ✓  
 11/09/01 ✓ 20 ✓

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 73449**

Thursday, September 01, 2011 7:31:06 AM



Page 2

Item ID: D3465-1

Accept



Setup

Start



Revision ID:

Item Name: Washer

Stop



Start Date: 8/31/2011 Start Qty: 20.00



Cust Item ID:

Required Date: 9/16/2011 Req'd Qty: 20.00



Customer:

Reference:

Approvals: Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run

Start



QC: \_\_\_\_\_

Date: \_\_\_\_\_

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop

Sequence ID/  
Work Center ID

130



Small Fab

Operation  
Description

Small Fab

Set Up/  
Run Hours

0.00

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

140



QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

Memo

0.00

150



Packaging

Packaging

Identify as per dwg & Stock Location: ST54

0.00

Memo

0.00

20x 11-09-2011

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 73449**

Thursday, September 01, 2011 7:31:06 AM

Page 3

Item ID: D3465-1

Accept



Setup

Start



Revision ID:

Item Name: Washer

Stop



Start Date: 8/31/2011 Start Qty: 20.00



Cust Item ID:

Required Date: 9/16/2011 Req'd Qty: 20.00



Customer:

Reference:

Approvals: Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run

Start



QC: \_\_\_\_\_

Date: \_\_\_\_\_

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop

Sequence ID/  
Work Center ID

160



QC

Quality Control

Operation  
Description

QC21- Final Inspection - Work Order Release

Set Up/  
Run Hours

0.00

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

0.00

Memo

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

# Picklist Print

Thursday, September 01, 2011 7:31:03 AM

Page 1

Work Order ID: 73449



Parent Item: D3465-1



Parent Item Name: Washer

Start Date: 8/31/2011

Required Date: 9/16/2011

Start Qty: 20.00

Required Qty: 20.00

Comments: IPP REV. A 05.11.18 NEW ISSUE EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M303R1.000 		Purchased	No			100	f	34.5390	0.0218	0.458947			

303 Round Bar 1.00

Location	Loc Qty	Loc Code
MAT028	34.539	
116700	1.107	
117550	6.9	
117598	13.74	
118008	12.792	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	73449
Description: Washer	Part Number:	D3465-1
Inspection Dwg: D3465	Rev: B	Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

## X First Article      Prototype

Measured by:	<i>owl</i>	Audited by:	<i>SD</i>	Prototype Approval:	N/A
Date:	11/09/19	Date:	11.9.19	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	07.09.06	New Issue	KJ/JLM <i>✓</i>	<i>E</i>

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED <i>TH</i>	APPROVED <i>TH</i>	DRAWING NO. D3465
DATE 05.12.05		TITLE WASHER
		SCALE 2:1

RELEASED

05.12.05 *TH*



D3465-X

SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. *734419*

*011-09-15*

1) SPECIFICATION: D3465-X WASHER

DASH No.

WHERE 'X' IS THE SIZE PER THE FOLLOWING TABLE:

DASH No.	A (in)	B (in)	C (in)
-1	0.453	1.00	0.125



NOTES:

- 1) MATERIAL: AISI 303 SS ROUND BAR (REF. DART SPEC. M303R)
- 2) FINISH: NONE
- 3) IDENTIFY WITH P/N USING FINE POINT PERMANENT MARKER
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries